

Knowledge Base

[EnSURE™ Touch](#)

- [EnSURE Touch Powers Off During Operation](#)
- [Troubleshoot Wi-Fi Connection Issues and Solutions](#)
- [EnSURE™ Touch Only Reads 0 RLU](#)
- [Blurred or Distorted EnSURE Touch Screens](#)
- [Network Ports, IP Addresses, and Protocols](#)
- [Using Teamviewer to Receive Remote Support](#)
- [Performing a Quick Test](#)
- [CalCheck Negative Control Failing](#)
- [Failing Calibration: Troubleshooting Tips](#)
- [Setting specific plans and locations on Ensure Touch instruments registered to the same site.](#)

[View All 26](#)

[SureTrend Cloud](#)

- [Product Selection instructions for EnSURE Touch](#)
- [Importing SureTrend 4 data into SureTrend Cloud](#)
- [Migrating -Locations, Plans and Data from Sure Trend 3 to Sure Trend Cloud](#)
- [Domain Locks for SureTrend Cloud](#)
- [Uploading Logo images to an account , sites and locations using the logo and location image uploader.](#)
- [Importing Plans and Locations to SureTrend Cloud](#)
- [User is unable to register instrument to SureTrend™ Cloud Account](#)
- [Forgot Password](#)
- [Clearing Instrument Registration to SureTrend Cloud](#)
- [SureTrend Cloud Roles Breakdown](#)

[View All 19](#)

SureTrend 4

- [Database Connection](#)
- [Multiuser Distributed Network Installation](#)
- [Standard Installation](#)
- [Using Teamviewer to Receive Remote Support](#)
- [Server Installation](#)
- [Moving the Database](#)
- [Network Share Installation](#)

Reagents, Tests and Devices

Reagent and Test troubleshooting and common questions.

- [Obtaining low RLU results when surfaces or water samples are visibly contaminated.](#)
- [The role of ATP Hygiene monitoring to support successful environmental sanitation / disinfection processes.](#)
- [Causes of increasing RLU levels on a surface after cleaning and retesting.](#)
- [False Positive results InSite Listeria and InSite L. mono Glo.](#)
- [Testing for residual chemical interference \(quenching or increasing \) of Hygiena environmental surface ATP test results, using the Hygiena Positive control kit.](#)
- [Effects of Environmental Light and Temperature on Hygiena ATP test devices](#)

Hardware

- [Battery Basics](#)
- [Blurred or Distorted EnSURE Touch Screens](#)
- [Quick Boot vs Normal Boot](#)
- [Battery Not Charging](#)

- [Battery Replacement](#)

Connectivity

- [Connecting to Wi-Fi](#)
- [Troubleshoot Wi-Fi Connection Issues and Solutions](#)
- [Using Your Mac as a Wi-Fi Hotspot](#)
- [Using Your Windows 10 Computer as a Wi-Fi Hotspot](#)

EnSURE and SystemSURE Plus

- [Standard Installation](#)
- [CalCheck Verification with EnSURE and SystemSURE Plus](#)
- [Quick Boot vs Normal Boot](#)

CalCheck

- [CalCheck Verification with EnSURE and SystemSURE Plus](#)
- [Changing The CalCheck Battery](#)
- [Calibration Checks in Simulation Mode](#)

ATP

- [ATP Side By Side Evaluation Kit Instructions](#)